


### SH10008



SH10008	
JR.SH100*	
1	30A0056
2	52N0099
3	53O0060
4	55M0026
5	AZ0540
6	AZ03140
7	51A0131
*8	15O0055
*9	12B0117
*10	08G0012
*11	12B0172
*12	57A0279
*13	58F0115
*14	12H0076
*15	12A0135
*16	57A0310
17	13D0100
18	(2) 24D0019
19	12L0016

ATENCIÓN: Desmontar este cilindro sin el material adecuado es peligroso debido a la fuerza del muelle

CAUTION: Trying to disassemble this cylinder without proper material is dangerous because of the strong spring.

ATTENTION: Essayer de démonter le vérin sans le matériel adéquat devient dangereux à cause de la force du ressort.

**LARZEP S.A.**  
 Avda. Urutiaga, 6. 48269 MALLABIA (Vizcaya).Spain  
 P.O.Box,27. 20600 Eibar (Guipúzcoa). Spain  
 Tel. (+34) 943-171200 - Fax. (+34) 943-174166  
 e-MAIL: [hydraulic@larzep.com](mailto:hydraulic@larzep.com)  
[www.larzep.com](http://www.larzep.com)

**LARZEP HYDRAULIC (UK) LTD**  
 UNIT 1A PARK ROAD INDUSTRIAL ESTATE  
 CONSETT CO.DURHAM DH85PU. ENGLAND  
 Tel. (+44)- 1207-582266 - Fax. (+44)- 1207-583366  
 e-MAIL: [enquire@larzep.co.uk](mailto:enquire@larzep.co.uk)  
[www.larzep.com](http://www.larzep.com)